

Converter Code Sheet and K Factors

Inv #	7in Converter Codes	Blade #	Fin	Back Angle	K-Factor
01	275-15	18	Straight	28°	445k
02	275-16				
03	275-777	18	Straight	25°	435k
04	275-48	18	Full	25°	435k
04C	275-48 CNC	18	Full	25°	435k
05	275-17	18	Straight	22°	425k
06	275-77	17	Straight	25°	415k
07	275-7	17	Straight	22°	415k
08	275-8	17	Full	22°	415k
09	300-88	17	Full	25°	405k
10	300-8	17	Full	22°	385k
11	300-77	17	Straight	25°	
12	300-7	17	Straight	22°	
12C	300-7 CNC	17	Straight	22°	
13	300-12-12	16	Full	25°	
14	300-12	16	Full	22°	375k
15	300-11-11	16	Straight	25°	
16	300-11	16	Straight	22°	
17	300-66	15	Full	25°	365k
18	300-6	15	Full	22°	365k
19	300-55	15	Straight	25°	365k
20	300-5	15	Straight	22°	365k
20C	300-5 CNC	15	Straight	22°	365k
21	300-10-10	14	Full	25°	
22	300-10	14	Full	22°	
23	300-9	14	Straight	22°	
24	300-44	13	Full	25°	350k
25	300-4	13	Full	22°	350k
26	300-3	13	Straight	22°	350k
27	325-7	17	Straight	22°	
28	325-66	15	Full	25°	353k
28C	325-66 CNC	15	Full	25°	353k
29	325-6	15	Full	22°	353k
30	325-5	15	Straight	22°	353k
31	325-44	13	Full	25°	338k
32	325-4	13	Full	22°	338k
33	325-3	13	Straight	22°	338k
34	350-66	15	Full	25°	341k
34C	350-66 CNC	15	Full	25°	341k
35	350-6	15	Full	22°	341k
36	350-5	15	Straight	22°	341k
37	350-44	13	Full	25°	325k
38	350-4	13	Full	22°	325k
39	350-3	13	Straight	22°	325k
7in Converter Codes	Blade #	Fin	Back Angle	K-Factor	
40	375-66	15	Full	25°	329k
41	375-6	15	Full	22°	329k

Inv #	Spline
01	ALPG
02	350TH
03	200TH
04	359
05	764
06	F-21
07	F-21A
08	F-18X
09	F-33
10	F-33A
11	400TH

Inv #	MP
-8	1/8MP
-4	1/4MP
-0	STD MP

Inv #	Fin Code	Loose
01	N+++	↓
02	N++	
03	N+	
04	N	
05	AE++	
06	AE+	
07	AE	
08	AC	
09	A+	
10	A	
11	B	
12	BC	
13	C	
14	HC	
15	D	
16	HD	
17	E	
18	HE	Tight
19	BA/C	0.075
20	AC/C	0.15
21	AE/C	0.225
22	AE/B	.060 TIP
23	BC/C	0.075
24	C/C	0.15
25	HC/C	0.225
26	D/C	0.275

42	375-44	13	Full	25°	312k
43	375-4	13	Full	22°	312k
44	375-33	13	Straight	25°	312k
45	375-3	13	Straight	22°	312k
46	400-66	15	Full	25°	317k
47	400-6	15	Full	22°	317k
48	400-44	13	Full	25°	300k
49	400-4	13	Full	22°	300k
50	400-3	13	Straight	22°	300k
51	400-14	11	Full	22°	
52	425-66	15	Full	25°	305k
53	425-6	15	Full	22°	305k
54	425-44	13	Full	25°	288k
55	425-4	13	Full	22°	288k
56	425-3	13	Straight	22°	288k
57	425-14	11	Full	22°	
58	450-66	15	Full	25°	293k
59	450-6	15	Full	22°	293k
60	450-44	13	Full	25°	276k
61	450-4	13	Full	22°	276k
62	450-3	13	Straight	22°	276k
63	450-14-14	11	Full	25°	
64	450-14	11	Full	22°	
65	475-44	13	Full	25°	264k
66	475-14-14	11	Full	25°	
67	500-44	13	Full	25°	252k
68	500-4	13	Full	22°	252k
69	500-3	13	Straight	22°	252k
70	500-14-14	11	Full	25°	
71	250-18F17				
72	275-18F17				
73	250-19F17				
74	275-15-15				